


PLT File Export in CorelDraw

I normally save my designs in a Finished Folder and the PLT file in a PLT folder
The cutting path I normally set the width to 1pt

Fig 1



First save your design as a CorelDraw file, Fig 1, design ready to save as a CorelDraw file

Fig 2




Fig2
Select the cutting path, and move to the bottom left of the artboard in CorelDraw, with it still selected, choose Export from the File Menu

Fig 3




Fig 3
In the dialog box, select PLT -HPGL Plotter File in the Save As File Type, also make sure to select the tick box for Selected Only
The press OK, a new dialog box will open

Fig 4




Fig 4
In the HPGL dialog box, select the Advance Tab, Make sure to select the tick box for Remove Hidden Lines and set the Curve Resolution as in fig 4 which is 0.001 in the left box, and Inches in the right drop down list. Then press OK